

OSS
ORGANIZATION OF
SELF-INSURED SCHOOLS

October 30, 2009

MEMORANDUM FOR:
OSS JPA Liaisons

OSS Safety Officers

OSS Contact People

OSS Servicing Agents

SUBJECT: 12 Volt Chargers

12 volt chargers may seem innocent enough, but they should not be left unattended in a vehicle for extended periods of time. The attached photos are a result of a phone charger/docking station that overheated and started a fire. The safest approach is to unplug any device that is attached when a vehicle is turned off.

Henry Brock
Risk Manager

